

CONFIDENTIAL

DPS-5915

COPY 1 OF 2

November 26, 1958

Dear Dan:

As discussed during our October 30 and 31 visit, attached is an inventory of the property now in our possession which is involved in the "C" System.

This includes Items 8, 9, 33, 45C, and 47A, on Contract No. SC-21-54. This inventory should be transferred to Contract No. HF-32-27, as Government-furnished equipment.

None of this equipment was included in our inventory which we submitted to you on November 7, 1958.

Charlie
Charlie

CMH:pma

Attachment

ILLEGIB

CONFIDENTIAL

Encl #1
OPS-5915
10/1/58

PROPERTY INVENTORY INVOLVED IN "C" SYSTEM

November 26, 1958

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
157-1121	Projection Group	5
157-1123	Field Assembly	5
157-1012	Elbow Mirror	5
155-0004	Scanning Mirror	7
155-0014	Primary Mirror	10
155-0007	"G" Mirror	8
155-0008	"H" Mirror	6
155-0009	"I" Mirror	6
153-0001	Memory Units	6
111-0966 & 111-0967	Blanks for "G" & "H" Windows	5

In addition to the above, the following component parts for 157-1121 and 157-1123 should be transferred:

<u>Part No.</u>	<u>Quantity</u>
157-1101	2
157-1102	3
157-1103	3
157-1104	3
157-1105	3
157-1107	2
157-1108	3
157-1109	1
157-1110	2
157-1111	1
157-1112	3
157-1113	1
157-1114	2
157-1115	3
157-1116	3

In addition to the above, the following glass blanks should be transferred:

<u>Description</u>	<u>Quantity</u>
Calcium Fluoride, 3.36" dia. x 1.5" thick	7
Calcium Fluoride, 3.6" dia. x 1.45" thick	7
LAK-9 Blanks, 3.10" dia. x .9" thick	8
" " 3.50" dia. x .45" thick	8
" " 3.5" dia. x .40" thick	8
" " 3.60" dia. x .92" thick	8
Blanks for Scanning Mirror (two (2) of these are damaged)	6
Blanks for Primary Mirror (one (1) of these is damaged)	6
Fused Quartz Blanks, 8" dia. x 1½" thick	9
Fused Quartz Blanks, 6" dia. x ¾" thick	7
Blank #8814, 4½" dia. x ¾" thick	8
Blank #8820, 3½" dia. x 1" thick	1
Blank #8837, 3½" dia. x 1" thick	1

6 2 7
6 2 1
5 2 1
9 1 1